



1 Turn power switch to on on back of machine.



2 Press "Carrier" button until temperature says 266. Wait until speed reaches 3 before laminating.



3 After finished laminating, press "Cold."



4 Once speed reaches 0 shut power on back of laminator off.